OUT55625

Cilica

Cyllia.

P Ø32ØØ7Z
FM NPIC WASHDC
TO RUCSC/SAC OFFUTT AFB OMAHA NEB
RUCVAA/4Ø8Ø STRAT WG OL 19 BARKSDALE AFB LA
RUCVAA/2D RTS BARKSDALE AFB LA
RUEKDA/DIA WASHDC
RUECYH/NAVRECONTECHSUPPCEN SUITLAND MD
RUEPIA/CIA WASHDC
RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF
RUWGAA/2AF BARKSDALE AFB LA
BT
S E C R E T CITE NPIC 4426.

1965 MM 3 20 20 Z

15TH AF (FOR DI), SAC (FOR DIM/GOLDEN TREE/DOCR, DM 4) 2D AF (FOR DI).

- 1. CAMERA B 101 WAS USED IN MISSION 8014 FLOWN 29 APRIL 1965 4 MAY 1965
  PROCESSING WAS ACCOMPLISHED BY BARKSDALE.
  - 2. ORIGINAL NEGATIVE:

ANOMALIES.

- A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD WHERE NOT DEGRADED BY VEHICLE MANOUVERS AND/OR ATMOSPHERIC CONDITIONS.
- B. 9R SIDE: BOTH EDGES CONTAIN FINE EDGE FOG AND SMALL STATIC DISCHARGES. THE INBOARD EDGE ALSO CONTAINS INTERMITIENT MINOR ROLLER INDUCED STATIC DISCHARGES.
- C. 9L SIDE: MINOR STATIC DISCHARGES ARE PRESENT INTERMIT-TENTLY ON BOTH EDGES. THE INBOARD EDGE CONTAINS ROLLER INDUCED STATIC DISCHARGES THROUGHOUT THE FIRST HALF OF THE MISSION

RECORD. FRAMES 1006 TO 1012 ARE CREASED. FRAMES 1019 TO 1023 ALSO CONTAIN CREASES. A MANUFACTURER'S SPLICE IS PRESENT IN FRAME 729.

- D. BOTH SIDES: THE TITLED FRAMES ARE NUMBERED 0000 TO 2351.
- E. THERE WERE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING

GROUP 1

Chief from automatic

conservative and

definition

-2-

## 3. POSITIVE:

- A. THE PI SUITABILITY RANGES FROM FAIR TO GOOD. DEGRADATION IS DUE PRIMARILY TO VEHICLE MANOUVERS AND HAZE.
  - B. THE PRINTING AND PROCESSING ARE GOOD.
- C. THE CLOUD COVER IS APPROXIMATELY 25 PERCENT. GP-1. SECRET

-- END OF MESSAGE--